

## Repair instruction

Description: C2 C3 C4 (produced until 15 June 2000) Lip seal

Part number: 16175

Look for Service Centers, Point of Sale addresses and other information on: [www.thetford-europe.com](http://www.thetford-europe.com)

Version: V2

Date: 13/07/2006

Tools required: 


A

Unscrew the 8 screws on the seal cover and, take the seal cover off.



B

Ensure the two cut outs on the seal face upwards and line up with the two centre screws of the three positioned on either side of the seal cover.



C

Replace the seat cover.



13/07/2006

Description: C2 C3 C4 (produced until 15 June 2000) Lip seal

1